

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**


**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




**Figure 1.** 5% disodium tallowimino dipropionate with 2.25% phthalic acid  
at 25 and 50 degree C




**Figure 2:** Dynamic shear moduli measurements for samples with 5% disodium tallowimino dipropionate and 2.25% phthalic acid at 25 and 50 degree C



**Figure 3:** 5% disodium tallowiminodipropionate, 4% NH<sub>4</sub>Cl with different amount of phthalic acid (PA) at 25 C



**Figure 4.** Steady shear viscosity of different amount of oleamidopropyl betaine (BET-O) in presence of 3% KCl and 0.5% Phthalic Acid at 25 C



**Figure 5.** Dynamic shear moduli of different amount of oleamidopropyl betaine (BET-O) in presence of 3% KCl and 0.5% phthalic acid at 25 C.